


工艺流程图 FLOWCHART



铸件与模具设计
Design of casting & tools



蜡料处理系统
Wax treatment device



压射蜡模
Injection of the wax patterns



检查修整蜡模
Shaving & inspection for the wax patterns to remove the flash



型壳在恒温恒湿环境下干燥
The shells are drying at constant temperature and humidity



中频感应炉快熔炼浇注
Melting the alloy in high frequency induction furnace and then cast into the hot shells